


STANLEY

DUBUIS



NOMENCLATURE		
Rep	Nb	REFERENCE
1	2	02151
2	1	30100
3	1	30110
4	1	30113
5	1	30114
6	1	30117
7	1	30176
8	1	30427
9	1	32005
10	3	35077
14	1	68018
16	1	84010
17	1	84015
18	2	84017
19	1	PB84022
20	1	85002
21	1	85004
22	1	85005
23	1	85006V
24	1	85007
25	1	85010V
26	1	85011
27	1	85012
28	1	85028
29	4	AAEN07
30	6	AAIL08
31	5	BILL03.175
32	4	BILL05.55
33	1	J0260190X70
34	1	J2700300
35	1	JAE0290155
36	1	JAE0570115
38	1	JBS05.7
39	1	JBS06
41	1	J0528178PU70
42	1	JR222804
43	1	JUP142250
44	4	RCC0070090100
45	1	VAR12MUZ
46	1	VAR18MUZ
47	1	VAV05CV005
48	3	VAV05TT006
49	1	VAV08CV016
51	1	AAIS60
52	1	77031
53	1	85069
54	1	77502
55	1	78155
56	1	85070
57	1	85071
59	1	SGET3100390
60	1	85068
61	1	JUP404865
62	1	VAV04FH008Z
63	2	VAV08BF
64	1	VAV06HC025
69	1	30788
74	1	VAV05CV008
90	1	ZBINA420
250	1	35815C-07
251	1	85821C
253	1	78842C
255	1	84809C
258	1	77818C
261	1	85813V
262	1	85814V
263	1	85815V
264	1	85817
266	1	32819C
270	1	85888C
271	1	85881C
272	1	85884C

T-MPL1301-0413

Repair kit standard exchange
 Kit de réparation échange standard
 78842C : Rep. : 253 - JBR-MPL130 : Rep. : 33 - 34 - 35 - 36 - 38 - 39 - 41 - 42 - 43 - 59 - 61

MPL1301

Référence DUBUIS : MPL1301 ind.-